**REMARKS** 

Figure 3 is being revised so that the "Q" block labeled 421 (which is a quantizer) is

changed to be properly labeled as 321, and the "W" block labeled 422 (which is a filter) is

changed to be properly labeled as 322.

The changes are being made so that the reference numbers of Figure 3 conform to the

written specification (e.g., see paragraphs [0032]-[0040] of the application as originally filed).

No new matter is being added by these amendments.

The Commissioner is authorized to charge any underpayment or credit any overpayment

to Deposit Account No. 06-1325 for any matter in connection with this

response which may be required.

Respectfully submitted,

Date: August 10, 2009

/Jeffrey R. Kurin/ By:\_\_\_

Jeffrey R. Kurin

Reg. No. 41,132

FLIESLER MEYER LLP

650 California Street, 14<sup>th</sup> Floor

San Francisco, California 94108

Telephone: (415) 362-3800

Facsimile: (415) 362-2928

2